



# Telepítési utasítások



1hoo.



x2



**A** x8



**B** x8




**C** x8




**D** x8




**E** x16





**F** x8




**G** x4










**H** x16








č	MM		
1	1 998	x	194
2	946	x	423
3	1 630	x	117

Ks
2
2
2







**F** x8  
6x30mm  
1/4" x 1 3/16"




**E** x16  
4x35mm  
5/32" x 1 3/8"






5




**B** x2

Ø15mm  
Ø19/32"



x2




1

**B**


2

**B**



**B** x2

Ø15mm  
Ø19/32"




6

2

1

**B**



x2



